



Report Date: Thursday, May 02, 2019

Page 1 of 1

Service# 186628193

Problem: SJ STREET FLOODING

Address(I): 48 ST

APT:

Cross Street: 37 AVE

ZIP: 11101

Pct: 114

Borough: QUEENS

Compass Direction:

SegmentID:

Building ID: 0

Block:

Lot:

CMBD: 401

Location:

District:

Parcel:

Area: 4 QUEENS

Sub-Area: 401 QUEENS COMMUNITY BOARD 1

# of Calls:	N/A	Occurred Date:	N/A	Call Date:	08-11-2018 09:18 AM
Taken By:	12645	GRATE, TIERNEY		Request Date:	08-11-2018 09:18 AM
Responsibility:	SQN	SEWER MAINTENANCE-QUEENS N.		Source:	ECC- EMERGENCY COMMAND CENTER
Scheduled Date:	N/A	Start Date:	08-12-2018 09:55 AM	Priority:	Z- DEFAULT PRIORITY
Inspector:	3987	LANA, VINCENT		Inspection Date:	08-12-2018 10:20 AM
Resolution Code:	SJFR	STREET FLOODING RESOLVED		Resolution Date:	08-12-2018 10:20 AM
Customer Contact Requested:	N	Incident Date:	N/A	Due Date:	N/A

Primary Caller Information

Title:		Reference#	N/A	CallerKey: 186628193
Last Name:	NYPD	Evening Phone:	N/A	
First Name, MI:	14730	Cell Phone:	N/A	
Address:		Day Phone:	(516)369-8200	
City/State/Zip:		Call Date:	08-11-2018 09:18 AM	
Caller Comments:	AS PER NYPD - STREET FLOODING			

Log Type	Log Started	Log Ended	Log By	Comments
ESC	08-11-2018	N/A	12645-GRATE, TIERNEY	NOTIFIED YAP AT SQN Input By: TIERNEY GRATE on 8/11/2018 9:22:29 AM
INITIAL	08-12-2018	08-12-2018	5325-PETERS, ANTHONY	08-12-2018 0955-1020 YAP TRK#377CAMPBELL-LANA TRK#563REMOVED DEBRIS ON TOP OF GRATESFLUSHED ONE BASIN CONNECTION ALL TAKING WATER WORKING AT THIS TIME N/F/AINSPCTION COMPLETE 8*13*18 1007 AP Input By: ANTHONY A PETERS on 8/13/2018 10:03:00 AM

Work Order	Priority	Activity	Problem	Unit-ID	Asset	Initiated	Completed	Source	Maint-Type
844188707		SCF		CB431602	STIN	08-12-2018	08-12-2018		



WO# 844188707

Completed Storm Inlet Work Order

Report Date: Thursday, May 02, 2019

Page 1 of 2

Work Order#	844188707	Activity: SCF	FLUSH CATCH BASIN/CONNECTION	
Address:	48 ST		Pct: 114	Zip: 11101
Cross Street:	37 AVE			
Compass Direction:			Borough: QUEENS	
Building ID:	0	Block:	Lot:	CMBD: 401
Storm Inlet ID:	CB431602			
Address:	48 ST			
Qualifier:	ON 15 FROM 48TH ST 48TH ST/43RD ST			Map# QI137
Area:	4	4	Sub-Area: 401 QUEENS COMMUNITY BOARD 1	
Location :	Asset Location Comments: ON 15 FROM 48TH ST 48TH ST/43RD ST		District: 844188707	
	ON 15 FROM 48TH ST 48TH ST/43RD ST			
Initiated By:	7060	YAP, RICHMANN	Initiated: 08-12-2018 09:54 AM	Scheduled: N/A
Assigned To:	3987	LANA, VINCENT	Service# 186628193	Due: N/A
Authorization:	1177	ANELLO, THOMAS		
Crew:	S2	SEWER- 2 LABORERS		
Maint Type:				
Priority:				
Problem:				Permit#
Project:				Completed: 08-12-2018 10:20 AM
Source:				Out of Service: N
				Potential Service Request: N
WO Responsibility:	SQN	SEWER MAINTENANCE-QUEENS N.		
WO Comments:	08-12-2018 0955-1020 YAP TRK#377CAMPBELL-LANA TRK#563REMOVED DEBRIS ON TOP OF GRATESFLUSHED ONE BASIN CONNECTION ALL TAKING WATER WORKING AT THIS TIME N/F/AINSPCTION COMPLETE 8*13*18 1007 AP Caller Comments for SR #: 186628193.....AS PER NYPD - STREET FLOODING			

Work Order Log History

Log Type	Log Started	Log Ended	Log By	Comments

There are no user logs for this work order

Primary Caller Information

Primary Caller:	NYPD, 14730	Call Date: 08-11-2018 09:18 AM
Address:		



Report Date: Thursday, May 02, 2019

Page 2 of 2

Day Phone: (516)369-8200
Comments: AS PER NYPD - STREET FLOODING

Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
ESC	08-11-2018		12645-GRATE, TIERNEY	NOTIFIED YAP AT SQN Input By: TIERNEY GRATE on 8/11/2018 9:22:29 AM
INITIAL	08-12-2018	08-12-2018	5325-PETERS, ANTHONY	08-12-2018 0955-1020 YAP TRK#377CAMPBELL-LANA TRK#563REMOVED DEBRIS ON TOP OF GRATESFLUSHED ONE BASIN CONNECTION ALL TAKING WATER WORKING AT THIS TIME N/F/AINSPCTION COMPLETE 8*13*18 1007 AP Input By: ANTHONY A PETERS on 8/13/2018 10:03:00 AM

Activity Safety Messages: There are no Safety Messages for this asset's Activity Code

Asset Safety Messages: There are no Safety Messages for this asset



CSR# 186647407

Service Request Detail Report

Report Date: Thursday, May 02, 2019

Page 1 of 1

Service# 186647407

Problem: SZZ OTHER SEWER PROBLEM (USE COMMENTS)

Address(I): 37 AVE

APT:

Cross Street: 48 ST

ZIP: 11101

Pct: 114

Borough: QUEENS

Compass Direction: N

SegmentID:

Building ID:

Block:

Lot:

CMBD: 401

Location:

Area: 4 QUEENS

District:

Parcel:

Sub-Area: 401 QUEENS COMMUNITY BOARD 1

of Calls: N/A

Occurred Date: N/A

Call Date: 09-13-2018 11:49 AM

Taken By: 4767

MORALES, JANET

Request Date: 09-13-2018 11:49 AM

Responsibility: SQN

SEWER MAINTENANCE-QUEENS N.

Source: ECC- EMERGENCY COMMAND CENTER

Scheduled Date: N/A

Start Date: 09-15-2018 08:30 AM

Priority: Z- DEFAULT PRIORITY

Inspector: 4377

MARINELLI, JOSEPH

Inspection Date: 09-15-2018 08:35 AM

Resolution Code: S689

OTHER - SEE REMARKS

Resolution Date: 09-15-2018 08:35 AM

Customer Contact Requested: N

Incident Date: N/A

Due Date: N/A

Primary Caller Information

Title:

Reference#

N/A

CallerKey: 186647407

Last Name: MARINELLI

Evening Phone:

N/A

First Name, MI: JOSEPH

Cell Phone:

N/A

Address: SUPERVISOR SQN

Day Phone:

(718)353-6904

City/State/Zip:

Call Date: 09-13-2018 11:49 AM

Caller Comments: INSPECT AREA LETTER #169415

Log Type	Log Started	Log Ended	Log By	Comments
INITIAL	09-15-2018	09-15-2018	4377-MARINELLI, JOSEPH	Marinelli veh#334See s/r#186596855 sent to cmom for further investigation CCTV w/o#844168190. Input By: LINDA BUSH on 9/25/2018 10:58:04 AM



CSR# 186648366

Service Request Detail Report

Report Date: Thursday, May 02, 2019

Page 1 of 1

Service# 186648366

Problem: SZZ OTHER SEWER PROBLEM (USE COMMENTS)

Address(I): 37 AVE

APT:

Cross Street: 48 ST

ZIP: 11101

Pct: 114

Borough: QUEENS

Compass Direction: N

SegmentID:

Building ID:

Block:

Lot:

CMBD: 401

Location: DUPE TO CSR#186647407

District:

Parcel:

Area: 4 QUEENS

Sub-Area: 401 QUEENS COMMUNITY BOARD 1

of Calls: N/A

Occurred Date: N/A

Call Date: 09-15-2018 08:32 AM

Taken By: 4767

MORALES, JANET

Request Date: 09-15-2018 08:32 AM

Responsibility: SQN

SEWER MAINTENANCE-QUEENS N.

Source: ECC- EMERGENCY COMMAND CENTER

Scheduled Date: N/A

Start Date: 09-15-2018 08:32 AM

Priority: Z- DEFAULT PRIORITY

Inspector: 1026

ABRUSCI, JOHN

Inspection Date: 09-15-2018 08:32 AM

Resolution Code: SDUP

DUPLICATE

Resolution Date: 09-15-2018 08:32 AM

Customer Contact Requested: N

Incident Date: N/A

Due Date: N/A

Primary Caller Information

Title:

Reference#

N/A

CallerKey: 186648366

Last Name: MARINELLI

Evening Phone:

N/A

First Name, MI: JOSEPH

Cell Phone:

N/A

Address: SUPERVISOR SQN

Day Phone:

(718)353-6904

City/State/Zip:

Call Date: 09-15-2018 08:32 AM

Caller Comments: INSPECT AREA LETTER #169415

Problem Comments: UPE TO CSR#186647407

DISTRICT OFFICE
47 01 QUEENS BOULEVARD, SUITE 205
SUNNYSIDE, NY 11104
(718) 383-9566
FAX: (718) 383-9676

CITY HALL OFFICE
250 BROADWAY, SUITE 1802
NEW YORK, NY 10007
(212) 788-7370
FAX: (212) 513-7195



THE COUNCIL OF
THE CITY OF NEW YORK

JIMMY VAN BRAMER
DEPUTY LEADER
26TH DISTRICT, QUEENS

DEP-RECEIVED
COMMISSIONER'S OFFICE

2018 SEP 10 P 12:21

CHAIR
CULTURAL AFFAIRS,
& INTERNATIONAL
INTERGROUP RELATIONS

COMMITTEES
FINANCE
PUBLIC HOUSING
PARKS
MENTAL HEALTH

August 15, 2018


The Honorable Vincent Sapienza
Commissioner
New York City Department of Environmental Protection
59-17 Junction Boulevard
Flushing, NY 11373

Dear Commissioner Sapienza,

My office was contacted by Barth-Gross Electric Company, Inc. (46-02 37th Avenue, LIC, NY 11101) regarding the issue of street flooding at the intersection of 37th Avenue and 48th Street. Enclosed is a map highlighting the area.

I am requesting that the NYC Department of Environmental Protection assess the nearby sewage system and make repairs are necessary. Thank you in advance for your prompt response.

Sincerely,


Jimmy Van Bramer
New York City Council Deputy Leader
JVB:KM

S-FLAG

169415

8/15/2018

48th St - Google Maps

48th St





Image capture Nov 2017 © 2018 Google

New York

Google, Inc.

Street View - Nov 2017

5117691





**Environmental
Protection**

59-17 Junction Blvd.
Flushing, NY 11373

TICKLER:

**From the Commissioner's Office
Correspondence Routing Slip**

Log #: 169415

Date Routed 9/10/2018

Due Date 9/24/2018

Source Code: CTU

Priority Status Normal

Routing Information

Person Responsible: MOIRA LYN FABLE

cc: Lamberta

Bureau Responsible: BWSO

Instructions: Please handle as appropriate

Notes:

Letter Information

Primary Correspondent Information

Name: Jimmy Van Bramer **Organization:** The Council of The City of New York

Address:

47-01 Queens Boulevard, Suite 205

Sunnyside NY 11104

Secondary Correspondent Information (On Behalf Of)

Name: Electric Co. Inc. Barth-Gross **Organization:** Barth-Gross Electric Comp

Address:

46-02 37th Avenue

Long Island City NY 11101

Date of Letter: 8/15/2018

Reference Code: ELECTED

Location of Problem/ Account Information: Intersection of 37th Avenue and 48th Street

Subject of Letter: Flooding

Please respond to the attached correspondence as requested and return once closed out to Cynthia Dilan with Log Number indicated clearly. Please contact Cynthia at (718) 595-3478 or via e-mail if you have any questions.

169415



Report Date: Thursday, May 02, 2019

Page 1 of 1

Service# 186650170

Problem: SJ STREET FLOODING

Address(I): 48 ST

APT:

Cross Street: 37 AVE

ZIP: 11101

Pct: 114

Borough: QUEENS

Compass Direction:

SegmentID:

Building ID: 0

Block:

Lot:

CMBD: 401

Location:

District:

Parcel:

Area: 4 QUEENS

Sub-Area: 401 QUEENS COMMUNITY BOARD 1

# of Calls:	N/A	Occurred Date:	N/A	Call Date:	09-18-2018 02:20 PM
Taken By:	7261	GILMORE, MALARIE		Request Date:	09-18-2018 02:20 PM
Responsibility:	SQN	SEWER MAINTENANCE-QUEENS N.		Source:	ECC- EMERGENCY COMMAND CENTER
Scheduled Date:	N/A	Start Date:	09-18-2018 02:25 PM	Priority:	Z- DEFAULT PRIORITY
Inspector:	4377	MARINELLI, JOSEPH		Inspection Date:	09-18-2018 03:30 PM
Resolution Code:	SDOCB	DEBRIS ON CATCH BASIN		Resolution Date:	09-18-2018 03:30 PM
Customer Contact Requested:	N	Incident Date:	N/A	Due Date:	N/A

Primary Caller Information

Title:	Reference#	N/A	CallerKey: 186650170
Last Name: DEP	Evening Phone:	N/A	
First Name, MI: MANDELBAUM	Cell Phone:	N/A	
Address:	Day Phone:	(646)799-8842	
City/State/Zip:	Call Date:	09-18-2018 02:20 PM	
Caller Comments:	Car seen partially submerged in floodwaters at 48th Street and 37th Avenue in Queens		

Log Type	Log Started	Log Ended	Log By	Comments
ESC	09-18-2018	N/A	7261-GILMORE, MALARIE	Notified Ms. Bush at Qu north sewer maint Input By: MALARIE GILMORE on 9/18/2018 2:23:29 PM
INITIAL	09-18-2018	09-18-2018	5325-PETERS, ANTHONY	09*18*18 1315-1530 MARINELLI VEH#334REMOVED DEBRIS FROM TOP OF C/B GRATEBASIN FUNCTIONING N/F/AINSPCTION COMPLETE 9-25-18 1512 AP Input By: ANTHONY A PETERS on 9/25/2018 3:20:12 PM



WO# 844200199

Non-Completed Storm Inlet Work Order

Report Date: Thursday, May 02, 2019

Page 1 of 2

Work Order#	844200199	Activity: SA23	REPAIR BASIN-MINOR	
Address:	48 ST		Pct: 114	Zip: 11101
Cross Street:	37 AVE			
Compass Direction:			Borough: QUEENS	
Building ID:	0	Block:	Lot:	CMBD: 401
Storm Inlet ID:	CB431601			
Address:	48 ST			
Qualifier:	ON 20 FROM 37TH AV 37TH AV/NORTHERN BL			Map# QI137
Area:	4	4	Sub-Area: 401 QUEENS COMMUNITY BOARD 1	
Location :	Asset Location Comments: ON 20 FROM 37TH AV 37TH AV/NORTHERN BL		District: 844200199	
	ON 20 FROM 37TH AV 37TH AV/NORTHERN BL			
Initiated By:	WEBSERVICE	SERVICE, WEB	Initiated: 09-09-2018 12:02 AM	Scheduled: N/A
Assigned To:	12241	RYAN, RICHARD	Service# N/A	Due: N/A
Authorization:	1439	BERKELEY, JAIME		
Crew:				
Maint Type:	PROG	PROGRAMMATIC		
Priority:				
Problem:				Permit#
Project:				Completed: N/A
Source:				Out of Service: N
				Potential Service Request: N
WO Responsibility:	WRQ	QUEENS REPAIRS		

Work Order Log History				
Log Type	Log Started	Log Ended	Log By	Comments
SCBPTI	09-09-2018	N/A	WEBSERVICE- SERVICE, WEB	SA23 MINOR REPAIR REQUIRED Work Order was added by the Catch Basin Programmatic Technical Workflow Input By: WEB SERVICE on 9/9/2018 12:02:01 AM

There are no user logs for this work order

Activity Safety Messages: There are no Safety Messages for this asset's Activity Code



Report Date: Thursday, May 02, 2019

Page 2 of 2

Asset Safety Messages: There are no Safety Messages for this asset